SUPPLIER CHECKLIST EXAMPLE



1 WHAT SERVICES ARE REQUIRED?

Laser Cutting is the main service needed

We will also need some assembly work

Custom packaging will be required to protect finish

2 WHAT TECHNOLOGY IS NEEDED?

Auto Cad is a must

Need a prototype created first

Automated technology would be a plus

3 IS LOCATION A FACTOR?

Needs to be American owned & operated

Prefere the Southeast -within 3 days truck drive

Need to avoid customs

HOW MUCH INSIGHT INTO THE PROCESS DO I NEED?

Would prefer a physical FAI Inspection

Need to be able to tour facility

Need to accommodate internal QA visits

5 HOW IMPORTANT IS QUALITY AND DELVIERY TIME?

Tolerance must be within +/- ,005

Cosmetic finish

Delivery needed in 2 months

SUPPLIER CHECKLIST



WHAT TEC	HNOLOGY IS	NEEDED?	
IS LOCATION	ON A FACTOR	?	
HOW MUC	H INSIGHT IN	TO THE PROC	ESS DO I
		ALITY AND DE	